

Partial Roof Overview

Harold Wood Sports Association · Aerial imagery, 11 August 2026 · Drone Studio ·
Demonstration document

Please read first: this is not a roof survey.

We were flying near your grounds on 11 August and photographed part of your roof in passing. The imagery turned out detailed enough to be worth sharing, so we have written it up and are sending it to you free of charge.

Only a small part of the roof was photographed — one side of the building, in a single pass lasting under three minutes. There was no intention of producing a complete assessment, and this document should not be read as one. Most of the roof was never in shot: the far elevations, the rear slopes, the gutter lines and all the valleys.

How these images were taken

39 photographs along one side of the roof, three seconds apart, from roughly 23 metres above ground, at 100 and 48 megapixels. That resolution lets individual tiles be examined on screen. Nobody went onto the roof; no scaffolding, ladders or access equipment were needed. Flight time was under three minutes.



General view of the section covered, with the clock turret and part of the front elevation.

Two points worth looking at

Within the small section we photographed, two tiles show visible damage. Neither looks like an emergency, but both are the kind of thing that is cheap to put right now and expensive to ignore.

1. Cracked tile. One tile has split, with a fragment displaced and lifted clear of the surface. A gap of this kind lets water past the covering in wind-driven rain, and the loose piece can slide further in a storm.



Cracked tile with a displaced fragment. Full-resolution detail from 23 metres.

2. Missing section of tile, underlay exposed. Part of another tile is absent and what appears to be the green underlay membrane is visible through the opening. Where that happens, the covering at that point is doing nothing and the membrane alone is holding the weather out — and membranes degrade quickly once exposed to sunlight. Note the replacement tile immediately beside it, suggesting this area has needed attention before.



Opening in the covering with underlay visible, next to a previously replaced tile.

General condition of what we could see

Moss along the tile laps. Dark clumps have formed along the horizontal overlaps, heaviest on the shaded slopes. Moss holds water against the tile surface, and in freezing weather that trapped water accelerates surface breakdown. Loose growth also washes down into gutters and downpipes.



Moss along the laps, with white and orange lichen colonies across the tile faces.

Extensive lichen cover across most of what was photographed. Lichen itself is largely cosmetic, but its spread marks surfaces that stay damp for long periods. **Several previously replaced tiles** are visible, differing in colour from those around them — useful to know where past problems occurred. A number of **vent terminals and a rooftop condenser unit** sit on the main slopes; points where anything passes through the covering are the usual places for water ingress to begin.

What we would suggest

Within the area we could see, the roof appears sound in overall form: ridge lines run straight and there was no sign of sagging or widespread tile movement. The two damaged tiles are worth having a roofer look at, ideally before winter, along with clearing moss from the gutters. Everything else we saw is maintenance rather than repair.

What a complete survey would add

If it would be useful, we can fly the whole building properly: every elevation and slope, gutter lines and valleys, ridges and all penetrations, photographed systematically rather than in passing.

It is worth putting the two findings above in context: **they turned up in a three-minute pass over a small part of one side of the building.** The rest of the roof has not been looked at. A full survey would give you a documented picture of all of it, and a baseline to compare against next year rather than judging changes from memory.

Because a full survey means flying over your property deliberately rather than incidentally, we would ask you to sign a short consent form beforehand — a standard one-page document covering permission to fly over the site and how the imagery may be used. We can send it across for you to look at, with no commitment.

Important limitation

This document is a visual impression from aerial photographs of one part of the roof, taken on a single day. It is not a structural survey and we are not roofing contractors. Nothing in it should be treated as a professional condition report or relied upon in place of an inspection by a qualified roofer, who can examine the underside of the covering, the timbers and the guttering at close range.