

Fault Code: 135

Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 135 PID(P): P100 SPN: 100 FMI: 3/3 Lamp: Amber SRT:	High signal voltage detected at the engine oil pressure circuit.	None on performance.



Engine Oil Rifle Pressure Sensor Circuit

Circuit Description

The engine oil rifle pressure sensor is a variable resistance sensor used by the ECM to monitor the lubricating oil pressure. The engine oil rifle pressure sensor has three circuits: 5 volt supply, return, and signal circuits. The signal circuit voltage indicates the oil pressure in the oil rifle.

Component Location

The engine oil pressure sensor is located in the oil rifle.

Conditions For Running The Diagnostics

This diagnostic runs continuously when the generator set controller is active or when the engine is running.

Conditions For Setting The Fault Codes

The Engine Control Module (ECM) detected the engine oil pressure signal voltage was out of range high.

Action Taken When The Fault Code Is Active

- The generator set controller displays a warning fault immediately when the diagnostics runs and fails.
- A default value for the engine oil pressure reading is used.

Conditions For Clearing The Fault Code

- To validate the repair, start the engine and let it run for 1 minute at no load.
- The generator set controller will turn off the warning indicator immediately after the user presses reset.
- The "Reset All Faults" command in the recommended Cummins® electronic service tool or equivalent can be used to clear active faults.

Shoptalk

Possible causes of this fault code include:

- Malfunctioning or damaged engine wiring harness.
- Malfunctioning or damaged engine oil rifle pressure sensor.

Refer to Troubleshooting Fault Code 135 . (</qs3/pubsys2/xml/en/procedures/60/60-t05-135.html>)