

# Fault Code: 141

## Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source

 Printable Version

### Overview

| Codes                                                                              | Reason                                                                          | Effect               |
|------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|----------------------|
| Fault Code: 141<br><br>PID(P): P100<br>SPN: 100<br>FMI: 4/4<br>Lamp: Amber<br>SRT: | Low signal voltage or open circuit detected at the engine oil pressure circuit. | None on performance. |



Engine Oil Rifle Pressure Sensor Circuit

### Circuit Description

The engine oil rifle pressure sensor is a variable resistance sensor used by the ECM to monitor the lubricating oil pressure. The engine oil rifle pressure sensor has three circuits: 5 volt supply, return, and signal circuits. The signal circuit voltage indicates the oil pressure in the oil rifle.

## Component Location

The engine oil pressure sensor is located in the oil rifle.

## Conditions For Running The Diagnostics

This diagnostic runs continuously when the generator set controller is active or when the engine is running.

## Conditions For Setting The Fault Codes

The Engine Control Module (ECM) detected the engine oil pressure signal voltage was out of range low.

## Action Taken When The Fault Code Is Active

- The generator set controller displays a warning fault immediately when the diagnostics runs and fails.
- A default value for the engine oil pressure reading is used.

## Conditions For Clearing The Fault Code

- To validate the repair, start the engine and let it run for 1 minute at no load.
- The generator set controller will turn off the warning indicator immediately after the user presses reset.
- The "Reset All Faults" command in the recommended Cummins® electronic service tool or equivalent can be used to clear active faults.

## Shoptalk

Possible causes of this fault code include:

- Malfunctioning or damaged engine wiring harness.
- Malfunctioning or damaged engine oil rifle pressure sensor.

Refer to Troubleshooting Fault Code 141 . (</qs3/pubsys2/xml/en/procedures/60/60-t05-141.html>)