

# Fault Code: 143

## Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level

 Printable Version

### Overview

| Codes                                                                                                      | Reason                                                            | Effect                                      |
|------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------|---------------------------------------------|
| <p>Fault Code: 143</p> <p>PID(P): P100</p> <p>SPN: 100</p> <p>FMI: 1/18</p> <p>Lamp: Amber</p> <p>SRT:</p> | <p>Oil pressure is below the engine protection warning limit.</p> | <p>Possible reduced engine performance.</p> |



Engine Oil Rifle Pressure Sensor Circuit

### Circuit Description

The engine oil rifle pressure sensor is a variable resistance sensor used by the ECM to monitor the lubricating oil pressure. The engine oil rifle pressure sensor has three circuits: 5 volt supply, return, and signal circuits. The signal circuit voltage indicates the oil pressure in the oil rifle.

## Component Location

The engine oil pressure sensor is located in the oil rifle.

## Conditions For Running The Diagnostics

This diagnostic runs continuously when the generator set controller is active or when the engine is running.

## Conditions For Setting The Fault Codes

The Engine Control Module (ECM) detected the engine oil rifle pressure is below the engine protection limits.

## Action Taken When The Fault Code Is Active

- The generator set controller displays a warning fault immediately when the diagnostics runs and fails.
- The torque output of the engine will be reduced.

## Conditions For Clearing The Fault Code

- To validate the repair, operate the engine under load for at least 5 minutes.
- The generator set controller will turn off the warning indicator immediately after the user presses reset.
- The "Reset All Faults" command in the recommended Cummins® electronic service tool or equivalent can be used to clear active faults.

## Shoptalk

Possible causes of this fault code include:

- Lubricating oil level is above or below specification.
- Lubrication oil pressure sensor is malfunctioning.

Refer to Troubleshooting Fault Code 143 . (</qs3/pubsys2/xml/en/procedures/60/60-t05-143.html>)