

Fault Code: Multiple E

Multiple Fault Code E on the Engine Harness

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: Multiple E PID(P): SPN: FMI: Lamp: SRT: 00-381	The supply voltage from pin 16 of the OEM interface harness has: - Failed internally in the ECM - Been shorted to ground - An open circuit external in the ECM.	Multiple fault codes.

©Cummins Inc

Circuit Description

The ECM supplies the coolant level sensor and the remote accelerator position sensor with +5 VDC from pin 16. The ECM has common returns for all of the engine pressure sensors and all of the temperature sensors on pin 21. A failure on either of these wires will cause multiple fault codes.

Component Location

Refer to the engine diagrams.

Shoptalk

Look for open circuits in the common supply and return wires and shorts from battery or ground to the supply and return wires or defective ECM power supply. A failed pressure sensor can cause multiple fault codes.

Refer to Troubleshooting Fault Code t05-mfc04 (</qs3/pubsys2/xml/en/procedures/19/19-t05-mfc04.html>)

Last Modified: 19-Aug-2010
