



Technical Service Bulletin

Technical Service Bulletin: tsb090081	Released Date: 12-Oct-2009
External Oil Leak at Oil Pan	

External Oil Leak at Oil Pan

Core Issue

This Early Field Notification informs the field that a manufacturing issue could result in cracks and an external oil leak in the ISX oil pan.

Confirmation

ISX Family Engines starting with ESN 79387906, build date 20-August-09. This issue was corrected beginning with ESN 79388492, build date 25-August-09.

Symptoms and observations are external oil leaks initiating at an oil pan crack. Crack locations can be along a weld, or along the ribbed area in the shallow end of the pan.

Visual inspection of an oil pan leak location.

A manufacturing issue at the supplier that resulted in oil pan cracks.

None

Resolution

Replace the oil pan.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Last Modified: 12-Oct-2009
