



Technical Service Bulletin

Technical Service Bulletin: tsb100679

Released Date: 05-Mar-2008

New Turbocharger Wastegate Actuator

New Turbocharger Wastegate Actuator

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin announces the release of two revised turbocharger kits and two new turbine housing repair kits for ISX CM570 and QSX CM570 engines built 01 January 1999, or later.

The new kits contain a new wastegate valve with a hard-coated shaft to increase resistance to wear. Turbocharger kits, Part Numbers 4090042 and 4090043, have a new turbocharger part number contained in each kit. Turbine housing repair kit, Part Numbers 4090044 and 4025316, are superseded by Part Numbers 4955847 and 4955848, respectively.

The release date for the new turbocharger housing kits is 31 January 2008. The turbocharger kits will be released in the middle of 2008, due to existing inventory.

The ESN first is 79288950 for Part Number 4955847, and 79288239 for Part Number 4955848.

HX55 Turbocharger Kit, Part Number 4090042

Old Part Number	New Part Number	Description
3066211	Unchanged	1 Seal, o-ring
3679139	Unchanged	1 Seal, o-ring
3680324	Unchanged	1 Gasket, flange
3922794	Unchanged	1 Seal, o-ring
4026884	Unchanged	1 Gasket, turbocharger
4040844	4046127	1 Turbocharger

HX60 Turbocharger Kit, Part Number 4090043

Old Part Number	New Part Number	Description
3066211	Unchanged	1 Seal, o-ring
3679139	Unchanged	1 Seal, o-ring
3680324	Unchanged	1 Gasket, flange
3922794	Unchanged	1 Seal, o-ring

HX60 Turbocharger Kit, Part Number 4090043		
Old Part Number	New Part Number	Description
4026884	Unchanged	1 Gasket, turbocharger
4040849	4043620	1 Turbocharger
HX55 Turbine Housing Repair Kit, Part Number 4955847 (supersedes Part Number 4090044)		
Old Part Number	New Part Number	Description
3066211	Unchanged	1 Seal, o-ring
3529372	Unchanged	1 Nut, regular hexagon
3535399	Unchanged	1 Clamp, v-band
3679139	Unchanged	1 Seal, o-ring
3680324	Unchanged	1 Gasket, flange
3922794	Unchanged	1 Seal, o-ring
4026884	Unchanged	1 Gasket, turbocharger
4040843	4046126	1 Housing, turbine
HX60 Turbine Housing Repair Kit, Part Number 4955848 (supersedes Part Number 4025316)		
Old Part Number	New Part Number	Description
3066211	Unchanged	1 Seal, o-ring
3529372	Unchanged	1 Nut, regular hexagon
3539458	Unchanged	1 Clamp, v-band
3680324	Unchanged	1 Seal, o-ring
3679139	Unchanged	1 Gasket, flange
3922794	Unchanged	1 Seal, o-ring
4026884	Unchanged	1 Gasket, turbocharger
4040848	4043619	1 Housing, turbine

Last Modified: 05-Mar-2008
