



Technical Service Bulletin

Technical Service Bulletin: tsb101143	Released Date: 09-Jun-2003
Rocker Lever Support Capscrews	

Rocker Lever Support Capscrews

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Remove from your files Service/Parts Topic 96T3-1A and replace it with this topic. This topic corrects procedure 003-009 in the above mentioned manuals. The revised procedure has the correct torque value that **must** be used for both aluminum and cast-iron rocker shaft support assemblies.

This topic applies to M11 and ISM/QSM11 engines.

A new mounting capscrew has been released for the rocker lever supports for all M11 and ISM/QSM11 engines. The new capscrew is made of a higher grade material which does **not** allow a higher assembly torque. The new capscrew, Part Number 3080722, is a Class-10.9 capscrew. It replaces capscrew, Part Number 3067382, which is a Class-9.8 capscrew. The new capscrew was introduced in production on 10 April 1995 with engine serial number 34771894.

Last Modified: 09-Jun-2003
