



Technical Service Bulletin

Technical Service Bulletin: tsb101521

Released Date: 27-Oct-2004

New Oil Cooler Kit

New Oil Cooler Kit

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces a new Oil Cooler Kit, Part Number 4089900, which supersedes Oil Cooler Kit, Part Number 4089583.

New Kit Part Number 4089900		
Description	Part Number	Quantity
Capscrews 12 point (short)	4101867	4
Capscrews 12 point (long)	4101868	2
Oil cooler core gaskets (rubber flash)	4101869	3
Protective cover	4026420	1
Protective cover	4058956	1

The cooler core element, Part Number 4059460, is **no** longer included in the kit. If the element fails leak testing, a replacement can be ordered separately. Analysis has shown leaks occur at the mounting joints much more often than in the cooler core elements. Elements that do **not** leak do **not** need to be replaced.

It is important to leak test the cooler core element assembly as a unit using lubricating oil cooler test kit, Part Number 4918200, so leaks at the mounting joints can be identified. These leaks can **not** be identified by testing an individual cooler core element removed from the assembly. A cooler core element is replaced **only** if it is found to be leaking.

If **no** leaks are found and the engine serial number is in the range of 14023600 to 14050000 or 79000000 to 79012457 the gaskets and capscrews **only** are replaced.

The cooler core element is to be reused. If **no** leaks are found and the engine serial number is **not** in the above ranges, the cooler core elements are **not** to be removed. Check the capscrew torques and tighten to the specified torque.

Lubricating oil cooler leak test Procedures 007-003, Lubricating Oil Cooler and 007-007, Lubricating Oil Cooler Element have been updated to include the latest leak testing procedures. These procedures **must** be followed if an element is suspected of leaking. Cooler core elements that are **not** leaking, are **not** to be replaced.

Note : This is a product improvement, not subject to campaign.

Related Procedures

10-007-003-tr (/qs3/pubsys2/xml/en/procedures/10/10-007-003-tr.html)	Lubricating Oil Cooler (/qs3/pubsys2/xml/en/procedures/10/10-007-003-tr.html)
10-007-007 (/qs3/pubsys2/xml/en/procedures/10/10-007-007.html)	Lubricating Oil Cooler Element (/qs3/pubsys2/xml/en/procedures/10/10-007-007.html)

Last Modified: 27-Oct-2004