



Technical Service Bulletin

Technical Service Bulletin: tsb103911

Released Date: 16-Dec-2009

Turbocharger Procedure, Install Section Revision

Turbocharger Procedure, Install Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Install section torque value for the standard and Spirallock® nuts.

- ISX Automotive CM570, QSX13 CM570 and Power Generation CM570

The torque value for the standard nut was changed from 60 N•m [44 ft-lb] to 61 N•m [45 ft-lb]. The torque value for the Spirallock® nut was changed from 60 N•m [44 ft-lb] to 81 N•m [60 ft-lb].

- Automotive CM870

The mounting nut torque was changed from 88 N•m [65 ft-lb] to 102 N•m [75 ft-lb].

Related Procedures

10-010-033-tr
(/qs3/pubsys2/xml/en/procedures/10/10-010-033-tr.html)

Turbocharger
(/qs3/pubsys2/xml/en/procedures/10/10-010-033-tr.html)

Last Modified: 16-Dec-2009