



Technical Service Bulletin

Technical Service Bulletin: TSB160035

Released Date: 06-Apr-2016

Cooling Fan Drive Belt Shredding on Recreational Vehicle Applications

Cooling Fan Drive Belt Shredding on Recreational Vehicle Applications

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISX15 CM2350 X101 (**Only** Recreational Vehicle Applications with CPL4588 or CPL3606)
- ISX15 CM2250 (**Only** Recreational Vehicle Applications with CPL3606)

This improvement **only** applies to the ISX15 recreational vehicle (RV) ratings:

- ISX15 550RV
- ISX15 600RV

Issue

Symptom:

- Cooling fan drive belt shredding

Root Cause:

- Existing cooling fan drive, Option FA1614, and fan belt drive, Option FA1756, exhibit excessive cooling fan drive belt flap during rapid deceleration on a recreational vehicle applications. This cooling fan drive belt flap leads to the cooling fan drive belt jumping out of alignment.

Verification

- Verify the engine has experienced cooling fan drive belt shredding.
- Verify the engine is equipped with fan drive option FA1614 and fan belt drive option FA1756.



08r00417

Figure 1, Example of Belt Shredding

Resolution

Install the new cooling fan drive belt and automatic belt tensioner listed in the Service Parts Availability section below.

- See the corresponding Service Manual. Reference Procedure 008-002 in Section 8.
- See the corresponding Service Manual. Reference Procedure 008-080 in Section 8.

Service Parts Availability

Service parts are available. See Table 1.

Table 1, Service Parts

Part Description	Existing Part Number	Associated Option	Obsoleted	Superseded	New Part Number	Associated Option
Tensioner, Belt	3691281	FA1614	No	No	3691282	FA1683
Belt, V Ribbed	3682891	FA1756	No	No	3104420	FA1762

Part Compatibility

New cooling fan drive, Option FA1683, and fan belt drive, Option FA1762, can **only** be used on the RV ratings listed above because of the belt configuration.

Production Status

Table 2, Production Information		
ESN First	Build Date*	Engine Plant
79906263	2 March 2016	Jamestown Engine Plant
*Engine build date can be found on the engine dataplate.		

Document History

Date	Details
2016-4-1	Module Created