



Technical Service Bulletin

Technical Service Bulletin: TSB160060

Released Date: 06-Jul-2016

Action Needed When Calibrating Wirtgen® W200 and W200H Engine Control Module (ECM) to Retain Low Idle Speed and Grid Heater Parameter Settings

Action Needed When Calibrating Wirtgen® W200 and W200H Engine Control Module (ECM) to Retain Low Idle Speed and Grid Heater Parameter Settings

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

Engine:

- QSX15 CM570

Original Equipment Manufacturer (OEM):

- Wirtgen®

Models:

- W200
- W200H

Issue

- Select engine control module (ECM) calibration codes have different default values for the Low Idle Speed and Grid Heater parameters than those required by the original equipment manufacturer OEM.
- If the ECM is replaced or ECM save and restore function is not used or is interrupted during ECM calibration download, ECM parameter settings will **not** be restored to the correct values. This can result in incorrect idle speed and impair grid heater function.

Verification

For affected ECM calibration codes, see Table 1.

Table 1, ECM Calibration Codes Affected					
ECM Calibration Code	Generic/Customer	DO Option	SC Option	FR Option	Availability
N12028	Generic	DO1684	SC11374	FR10577	Service Only
N11835	Generic	DO1412	SC11374	FR10577	Service Only

Resolution

- If the ECM is replaced or ECM save and restore function is **not** used or is interrupted during ECM calibration code download, technicians **must** verify that the parameters are correct. For default Wirtgen® parameters settings, See Table 2 below.
- If an ECM calibration code update is required, ECM calibration codes **must** be updated on a like-for-like basis, with no change in the ECM base calibration code.

Table 2, Default Wirtgen® ECM Parameters	
Parameter	Nominal Wirtgen® Setting
Low Idle Speed	950 rpm
Grid Heater	On

Production Status

All engines built after 7 March 2016 will be loaded with ECM calibration code N12213.

Document History

Date	Details
2016-6-9	Module Created

Last Modified: 06-Jul-2016
