



Technical Service Bulletin

Technical Service Bulletin: TSB170064

Released Date: 16-May-2017

Injector Fault Codes 1139, 1141, 1142, 1143, 1144, or 1145

Injector Fault Codes 1139, 1141, 1142, 1143, 1144, or 1145

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

Engine:

- X15 CM2350 X114B
- X15 CM2350 X116B

Build Date Range:

- 1 May 2016 to 3 February 2017

Issue

Symptoms:

- Fault Code(s) 1139, 1141, 1142, 1143, 1144, or 1145 becoming active prior to chassis reaching 8,047 km [5,000 miles].

Root Cause:

- Fueling adaption error in engine control module (ECM).

Verification

Engine **must** have a build date between 1 May 2016 and 3 February 2017.

Resolution

- Connect INSITE™ electronic service tool
- Troubleshoot any other fault codes **not** listed above first
- Select Advance ECM Data
- Select Fuel Injector Reset
- Reset all Injectors
- Clear all fault codes

- If Fault Code(s) 1139, 1141, 1142, 1143, 1144, or 1145 becoming active again, perform published troubleshooting

Document History

Date	Details
2017-5-12	Module Created

Last Modified: 16-May-2017
