



Technical Service Bulletin

Technical Service Bulletin: TSB170085

Released Date: 08-Apr-2026

Fault Code 5867: PACCAR™ Chassis with Battery Disconnect Switch

Fault Code 5867: PACCAR™ Chassis with Battery Disconnect Switch

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Information Only - OEM Related Matter Not Covered By Cummins® - Contact Appropriate OEM Dealer or OEM Representative For Additional Information

Contents

Product Affected

Engines:

- B6.7 CM2350 B121B
- ISB6.7 CM2350 B142
- ISL9 CM2350 L111
- L9 CM2350 L116B
- X12 CM2350 X119B
- X12 CM2450 X137B
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2450 X124B
- X15 CM2450 X134B
- X15 CM2450 X142B

Original Equipment Manufacturer (OEM):

- PACCAR™ (Peterbilt or Kenworth chassis)
- **Only** units equipped with battery disconnect switch

Issue

Symptom:

- Fault Code 5867 (Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source) often leading to unnecessary replacement of OEM diesel exhaust fluid (DEF) pump relay or other components.

Root Cause:

- PACCAR™ chassis do **not** provide a dedicated power source to the aftertreatment DEF dosing unit. Units equipped with battery disconnect switches can interrupt the DEF system power down and purge sequence, logging Fault Code 5867.

Verification

- If unit is equipped with a battery disconnect switch; clear fault codes, turn key to OFF position for two minutes, turn key to ON position and see if Fault Code 5867 returns. If Fault Code 5867 does **not** return after being cleared, see Resolution section below.

Resolution

- Verify notification sticker directing proper power down procedures is affixed to chassis near battery disconnect switch. Contact local PACCAR™ support location for battery disconnect power notification sticker See Figure 1 below.
- Inform operator of proper power down procedure which requires two minutes before disconnecting power using battery disconnect switch.




Figure 1, Battery Disconnect Direction Sticker.

Document History

Date	Details
2017-7-14	Module Created

Date	Details
2018-10-31	Added B6.7 CM2350 B121B and L9 CM2350 L116B to list.
2021-2-16	Clarified that PACCAR™ is defined as Peterbilt or Kenworth chassis.
2021-3-8	Updated Figure 1.
2026-3-12	Updated product affected list to include X137B, X119B, X124B, X134B and X142B.
2026-4-8	Fixed ECM number on X124B listed in product affected list to show correctly as CM2450 rather than CM2350.

Last Modified: 08-Apr-2026
