



Technical Service Bulletin

Technical Service Bulletin: TSB190140

Released Date: 19-Aug-2019

Introduction of a New Switch Pressure

Introduction of a New Switch Pressure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- KTTA-19-C (Industrial Only)

Description of Change

This document announces an introduction of new stainless steel fuel switch pressure for KTTA-19-C engine model. Hence, a new stainless steel fuel switch pressure is introduced, which has higher yield strength, higher tensile strength and lower elongation than brass material so to withstand pressure hammering effect better than brass material.

Reason for Change

It was observed that there were fuel leakages from the electrical connector through breather hole. These fuel leakages may led to excessive fuel delivery to piston and consequentially heavy white smoke was observed.

Service Parts Availability

Service parts are available. See Table 1.

Table 1, Switch, Pressure Part Numbers

Part Description	Existing Part Number	New Part Number
Switch, Pressure	2897690	5462262

Part Compatibility

This part cannot be mixed within the same engine because of modification done and this part is compatible as per Table 1 **only**.

Part Structure

The old part number should be replaced with the new part number.

Part Inventory Action

The old part numbers in stock should **not** be used.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information		
Engine Seriel Number (ESN) First	Build Date*	Plant
25440131	06 December, 2018	KCL, Cummins India LTD.
*Engine build date can be found on the engine dataplate.		

Document History

Date	Details
2019-8-9	Module Created