



Technical Service Bulletin

Technical Service Bulletin: TSB190195

Released Date: 09-Dec-2019

Introduction of Twin Oil Hole Rocker Lever in K19 Engine

Introduction of Twin Oil Hole Rocker Lever in K19 Engine

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- K19 (Industrial only)

Description of Change

This document announces an introduction of new twin oil hole rocker lever in K19 Powercar application engine model.

Reason for Change

Fretting wear was observed on the crosshead and rocker lever, hence there was metal to metal contact between the crosshead and rocker lever. There were heavy progressive damages observed on the crosshead and valve due to continuous engine operation with excessive valve lash.

Service Parts Availability

Service parts are available. See Table 1.

Table 1, Cylinder Head Part Numbers

Part Description	Old Part Number	New Part Number
Lever, Rocker	3053476	3394683
Lever, Rocker	3053477	3394684

Part Compatibility

This part cannot be mixed within the same engine because of modification done and this part is compatible as per Table 1 **only**.

Part Structure

The old part number should be replaced with the new part number.

Part Inventory Action

The old part numbers in stock should **not** be used.

Production Status

Implemented for production. See Table 2.

Table 2, Plant Information

Engine Serial Number (ESN) First	Build Date*	Plant
25441513	04 November 2018	KCL, Cummins India LTD.

*Engine build date can be found on the engine dataplate.

Document History

Date	Details
2019-11-14	Module Created

Last Modified: 09-Dec-2019
