



Technical Service Bulletin

Technical Service Bulletin: TSB200038

Released Date: 24-Feb-2020

Lubricating Oil Pump Noise

Lubricating Oil Pump Noise

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISX CM570
- ISX CM870
- ISX CM871
- ISX CM871 E
- ISX15 CM2250
- ISX15 CM2250 SN
- ISX15 CM2350 X101
- QSX15 CM2250
- QSX15 CM2250 ECF
- QSX15 CM2250 X115
- QSX15 CM2350 X105
- QSX15 CM2350 X106
- QSX15 CM2350 X118
- QSX15 CM570
- X15 CM2350 X116B

Issue

A new heavy-duty lubricating oil pump, Part Number 5532492, is experiencing unusual noise characteristics.

This issue may be experienced on engines equipped with part option LP1745.

Symptom:

- A buzzing noise originating from the front of the lubricating oil pan.
- Buzzing noise from the front of the lubricating oil pan is usually present at idle with cold lubricating oil but can also be present at higher engine rpm and at warmer lubricating oil temperatures in some cases.

Root Cause:

- Buzzing noise from the front of the lubricating oil pan is caused by a pulsation frequency from the lubricating oil pump.

Verification

- Operate the engine at idle:
 - Listen for a high frequency buzzing coming from the front of the lubricating oil pan.
 - The noise should be softer as one moves away from the lubricating oil pan.

Resolution

- No action is to be taken.
- This buzzing noise will **not** harm the engine.
- A solution is being developed and is **not** available yet. This document will be updated when a solution is found.

Document History

Date	Details
2020-2-24	Module Created

Last Modified: 24-Feb-2020
