



Technical Service Bulletin

Technical Service Bulletin: TSB200098

Released Date: 04-Feb-2021

New Accessory Drive Support

New Accessory Drive Support

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK23 CM500 FCO

Issue

The accessory drive support front bearing experiences increased radial load due to the fitted 140A alternator configuration and increase in overhang.

Symptom

- Excessive noise from the front of the engine
- Accessory drive support front bearing malfunction. See Figure 1.

Root Cause

- Excessive load applied to the accessory drive support front bearing.



Figure 1, Disassembled Accessory Drive Support, Front Bearing In Red Box

Verification/Confirmation

- Engine is equipped with 140A alternator.
- Accessory drive support front bearing malfunction.

Resolution

- A new accessory drive support with a front cylindrical roller bearing has been released.
- Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number	Quantity Needed
Drive, Fuel Pump / Support, Accessory Drive	4096329	Yes	Yes	5633425	1

Part Compatibility

Accessory drive support, Part Number 4096329, can **only** be used for 75A alternator configurations.

The new accessory drive support, Part Number 5633425, with cylindrical roller bearing is compatible with both the 75A and 140A alternator configurations.

Once Part Number 4096329 stock is exhausted, use Part Number 5633425.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information

ESN First	Build Date ¹	Plant
85006853	16 October 2019	Phalton Engine Plant

¹Engine build date can be found on engine dataplate.

Document History

Date	Details
2020-4-21	Module Created

Last Modified: 04-Feb-2021
