



Technical Service Bulletin

Technical Service Bulletin: TSB200210

Released Date: 21-Oct-2020

Fault Code 6637 on PACCAR™ Chassis with Horton® Fan Controller

Fault Code 6637 on PACCAR™ Chassis with Horton® Fan Controller

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Information Only - OEM Related Matter Not Covered By Cummins® - Contact Appropriate OEM Dealer or OEM Representative For Additional Information

Contents

Product Affected

This issue is unique to Kenworth™ and Peterbilt™ units equipped with Horton® fan controller.

- X15 CM2350 X114B
- X15 CM2450 X124B

Issue

Symptom:

- Fault Code 6637 is active or has inactive counts.
- Amber service lamp intermittently illuminates.

Root Cause:

- Horton® fan controller (OEM part with firmware part number 230023) sends "Fan speed signal >100%" to engine control module (ECM) causing FC6637 to become active.

Verification

- The firmware version of the fan controller can be found on the back label of the fan controller.
- Confirm unit has fan controller with old firmware, part number 230023.



Figure 1, Horton® Fan Controller

Resolution

- This issue is unique to PACCAR™ chassis. All claims and parts should be sourced appropriately through PACCAR™.
- Contact the OEM for the appropriate part number, reference Horton® Product Technical Bulletin PTB 2020.
- Horton® has released an updated fan controller under the existing assembly part number.
- The firmware part number located on the back of the fan controller has been updated.

Document History

Date	Details
2020-10-21	Module Created

Last Modified: 21-Oct-2020