



Technical Service Bulletin: TSB210017

Released Date: 29-Jan-2021

False Occurrences of Fault Code 3492 or 3656 Caused by AutoStart Feature

## False Occurrences of Fault Code 3492 or 3656 Caused by AutoStart Feature

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

#### Product Affected

- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2450 X124B
- X15 CM2450 X134B

#### Issue

Symptom:

- Engine with AutoStart feature has active Fault Codes 3492, 3656, or has more than one inactive count within the last 25 engine operating hours.

Root Cause:

- The interaction between the AutoStart system and an engine diagnostic to detect errors in the engine off timer has caused a false occurrence of this fault code.

#### Verification

- Verify unit is equipped with AutoStart system and system was in use recently.

#### Resolution

- Troubleshoot active or inactive fault codes with more than one count in the last 25 engine hours.
- Engine control module (ECM) calibration code to address this issue will be available in second quarter of 2021.
- Do **not** replace the ECM for this issue.

# Document History

| Date      | Details        |
|-----------|----------------|
| 2021-1-26 | Module Created |

---

Last Modified: 29-Jan-2021

---