



Technical Service Bulletin

Technical Service Bulletin: TSB210045

Released Date: 10-Mar-2021

Lubricating Oil Pressure Regulator Update: Low Lubricating Oil Pressure Fault Code 143

Lubricating Oil Pressure Regulator Update: Low Lubricating Oil Pressure Fault Code 143

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSM CM570
- QSM11 CM876 M101
- QSM11 CM876 M102M

Issue

Symptom:

- Low oil pressure Fault Code(s) 143 coupled with fluctuating oil pressure at or near rated speed. In some cases, the upfit described herein may be appropriate in cases of high lubricating oil pressure fluctuation even if no fault code is present, at Cummins Inc. discretion.

Root Cause:

- Lubricating oil pressure regulator orifice (known as the viscosity sensor) is **not** restrictive enough to support stable lubricating oil pressures at high lubricating oil temperatures that typically occur at or near rated speed.

Verification

- Verify that lubricating oil pressure fluctuation is present and other troubleshooting measures have been exhausted

Resolution

- A new orifice plug that has been released. This part replaces the viscosity sensor and is more restrictive, promoting oil pressure stability.
- Replace viscosity sensor, Part Number 3069728, with orifice plug, Part Number 5568108.
- A new pressure regulator plunger that **must** be used in conjunction with the above-mentioned orifice plug. This part replaces the existing pressure regulator plunger and is also more

restrictive.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Sensor, Viscosity	3069728	Yes	Yes	5663305
Plunger, PRS Regulator	3068979	Yes	Yes	5663305

Document History

Date	Details
2021-2-23	Module Created

Last Modified: 10-Mar-2021
