



Technical Service Bulletin: TSB210275

Released Date: 24-Jan-2023

Air Handling Performance Test Available to Diagnose Restricted Exhaust Gas Recirculation (EGR) Cooler

Air Handling Performance Test Available to Diagnose Restricted Exhaust Gas Recirculation (EGR) Cooler

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B6.7 CM2350 B121B
- B6.7 CM2450 B155B
- L9 CM2350 L116B
- L9 CM2450 L126B
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2450 X124B
- X15 CM2450 X134B

Issue Summary

Engine experiences one or more of the following fault codes:

- 3342, 3361, 3382, 3383, or 3389

Verification

- New Air Handling Performance Test is used when troubleshooting certain engine fault codes. Throughout the test engine speed and the position of air handling actuators are controlled to create conditions for the various diagnostics to run.
- To determine the health of the EGR cooler, the Air Handling Performance Test raises exhaust gas recirculation (EGR) flow and assesses both the restriction level and thermal effectiveness of the EGR cooler.
- The Air Handling Performance Test is to be performed when directed by troubleshooting to verify the root cause of malfunction is identified and repaired the first time without unnecessary component replacements. The Air Handling Performance Test is presently being

used by Guidanz®, EDS, and QuickServe® Online (QSOL) troubleshooting for multiple ECM fault codes.

Resolution

- Perform the Air Handling Performance Test when directed by published troubleshooting.
- Reference the appropriate Fault Code Troubleshooting procedure. See corresponding Service Manual. Reference Procedure 014-032 in Section 14.
- The EGR cooler should **only** be replaced when directed by the Air Handling Performance Test. Visual inspection should **not** drive the replacement of restricted EGR coolers.

Description of Change

- This document is intended to highlight the ability of the Air Handling Performance Test to diagnose EGR cooler problems.
- The Air Handling Performance Test is now available. This diagnostic test was developed to evaluate the health of components in the air handling system.
- The Air Handling Performance Test can accurately identify plugged or otherwise restricted EGR coolers. The use of this diagnostic test reduces the chance of a repeat fault code event for the customer because of EGR cooler misdiagnosis.

Publications Affected

Table 1, Publications Affected

Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	B6.7 CM2350 B121B	5411223	Air Handling Performance Test	Refer to Procedure 014-032 (/qs3/pubsys2/xml/en/procedures/455/455-014-032.html)	14
Service Manual	B6.7 CM2450 B155B	5613229	Air Handling Performance Test	Refer to Procedure 014-032 (/qs3/pubsys2/xml/en/procedures/647/647-014-032.html)	14

Table 1, Publications Affected					
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	L9 CM2350 L116B	5411330	Air Handling Performance Test	Refer to Procedure 014-032 (/qs3/pubsy s2/xml/en/pr ocedures/45 9/459-014-032.html)	14
Service Manual	L9 CM2450 L126B	5613077	Air Handling Performance Test	Refer to Procedure 014-032 (/qs3/pubsy s2/xml/en/pr ocedures/58 3/583-014-032.html)	14
Service Manual	X15 CM2350 X114B	5411181	Air Handling Performance Test	Refer to Procedure 014-032 (/qs3/pubsy s2/xml/en/pr ocedures/37 7/377-014-032.html)	14
Service Manual	X15 CM2350 X116B	5411186	Air Handling Performance Test	Refer to Procedure 014-032 (/qs3/pubsy s2/xml/en/pr ocedures/45 3/453-014-032.html)	14
Service Manual	X15 CM2450 X124B	5504583	Air Handling Performance Test	Refer to Procedure 014-032 (/qs3/pubsy s2/xml/en/pr ocedures/56 4/564-014-032.html)	14

Table 1, Publications Affected					
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	X15 CM2450 X134B	5613373	Air Handling Performance Test	Refer to Procedure 014-032 (/qs3/pubsyss2/xml/en/procedures/643/643-014-032.html)	14

Document History

Date	Details
2021-12-10	Module Created
2022-1-11	Updated Table 1.
2023-1-24	Added additional products to product affected list and table.

Last Modified: 24-Jan-2023
