



Technical Service Bulletin: TSB250170

Released Date: 05-Sep-2025

Injector Rocker Lever Adjusting Screw Improvement: Low Power, High Blowby, and Engine Noise

Injector Rocker Lever Adjusting Screw Improvement: Low Power, High Blowby, and Engine Noise

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK23 CM500
- QSK78 CM500

Issue Summary

Symptom:

- Engine will exhibit low power, high blowby, and noise coming from inside the rocker lever cover.

Root Cause:

- Injector rocker lever adjusting screw fracturing at the location of the horizontal oil drilling.
- The dimensions of the horizontal oil drilling of the injector rocker lever adjusting screw are out of specification.

Verification

Verify malfunctions of the injector rocker lever adjusting screw fracturing at the location of the horizontal oil drilling.

Resolution

The dimensions of the horizontal oil drilling of the rocker lever adjusting screw have been revised and are now in specification.

Service Parts

Service parts are offered. See Table 1 for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Rocker Lever Adjusting Screw	4096493	No	No	-

Part Identification

All injector rocker lever adjusting screws with the updated dimensional controls will be denoted with a green paint mark on the rocker lever assembly (See Figure 1) and a laser etching with the letter "A" on the top of the injector rocker lever adjusting screw (See Figure 2).



Figure 1, Rocker Lever Assembly.

- "A" mark provided on the screw top face to eliminate part misidentification.
- Green dot identification mark on the lever forging area.



Figure 2, Injector Rocker Lever Adjusting Screw.

Document History

Date	Details
2025-9-5	Module Created

Last Modified: 05-Sep-2025
