



Technical Service Bulletin: TSB180065

Released Date: 26-Jun-2018

Navistar Engine Control Module (ECM) Programmable Parameters

Navistar Engine Control Module (ECM) Programmable Parameters

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Information Only - OEM Related Matter Not Covered By Cummins® - Contact Appropriate OEM Dealer or OEM Representative For Additional Information

Contents

Product Affected

Engines:

- X15 CM2350 X101
- L9 CM2350
- B6.7 CM2350

Original Equipment Manufacturer (OEM):

- Navistar

Chassis:

- LT
- HV
- MV

Issue

Symptom:

- Fault Codes 2222 and 6261
- Features and parameters are erased when performing an engine control module (ECM) calibration download via 9 pin connector.

Root Cause:

- Door controllers or "door pods" will interfere with data transfer required when calibrating the ECM, which prevents features and parameters from installing.

Resolution

- Perform ECM calibrations using 3 pin connector.
- Create an ECM calibration code template in case ECM calibration code download malfunctions.
- Remove door controller fuses before performing an ECM calibration code download using 9 pin connector.
- Reference iKNow article IK2600236 for further instructions.

Document History

Date	Details
2018-5-22	Module Created
2018-6-26	Updated warranty statement to "NOOEM"

Last Modified: 26-Jun-2018
