



Technical Service Bulletin

Technical Service Bulletin: TSB190112

Released Date: 14-Jan-2020

Crank No Start Condition: Units Equipped with Endurant™ Transmission

Crank No Start Condition: Units Equipped with Endurant™ Transmission

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Information Only - OEM Related Matter Not Covered By Cummins® - Contact Appropriate OEM Dealer or OEM Representative For Additional Information

Contents

Product Affected

- X15 CM2350 X114B
- X15 CM2350 X116B
- X12 CM2350 X119B

Issue

Symptom:

- Units equipped with Eaton™ Endurant™ transmission experience a crank no start event with or without transmission fault codes.
- The following transmission fault codes may be present:
 - 511 (SPN 5614 FMI 16)
 - 513 (SPN 5616 FMI 16)
 - 514 (SPN 5617 FMI 16)
 - 636 (SPN 5903 FMI 15)
 - 637 (SPN 4216 FMI 15)

Root Cause:

- Fueling to the engine has been disabled, resulting in a crank no-start condition without logging fault codes.

Verification

- Turn keyswitch ON.
- Crank the engine.
- Verify crank no-start condition.

- Stop engine cranking.
- Disconnect the datalink harness to the transmission. See equipment manufacturer service information.
- Verify the engine cranks and starts.
- Turn keyswitch OFF.
- Reconnect the vehicle wiring harness at the transmission. See equipment manufacturer service information.

Resolution

- This condition has been resolved in Eaton™ Endurant™ TCM software version 5516018.

Document History

Date	Details
2019-6-27	Module Created
2020-1-13	Update to multiple sections.

Last Modified: 14-Jan-2020
