



Technical Service Bulletin

Technical Service Bulletin: TSB210020

Released Date: 18-Dec-2024

Allison Transmission® Fault P2637 Caused by Engine Control Module (ECM) Calibration

Allison Transmission® Fault P2637 Caused by Engine Control Module (ECM) Calibration

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B6.7 CM2450 B155B
- L9 CM2350 L116B
- L9 CM2450 L126B
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2450 X124B
- X15 CM2450 X134B
- X15 CM2450 X142B

Issue

Symptom:

- CHECK TRANSMISSION lamp is illuminated
- Shift quality issues and gear limitation
- Active or inactive Allison Transmission® fault P2637

Root Cause:

- Engine control module (ECM) calibration code

Verification

- Verify Allison Transmission® fault code P2637 is active or has inactive counts.
- Compare the ECM code and revision number in the ECM to the calibration revision listed in the ECM calibration revision history on QuickServe® Online (QSOL) for applicable changes.

Resolution

- Cummins Inc. is releasing ECM calibration revisions that reduce occurrences of Allison Transmission® fault P2637. Timing availability of the ECM calibration improvement will vary

by engine service model name. See Table 1 below.

- If an ECM calibration update for this issue is available, the ECM calibration revision **must** be that revision or higher.
- If ECM calibration revision is **not** yet available for one of the listed engine service model names, cycling the key can temporarily extinguish the CHECK TRANSMISSION lamp and return the vehicle to normal operation until the fault comes active again.
- If the ECM already contains the ECM calibration improvement for P2637, reference the OEM or Allison Transmission® service processes.

Table 1, ECM Calibration Code Availability

Service Model Name	P2637 Calibration Improvement Available	Production Implementation Date	QuickServe® Online (QSOL) ECM Calibration Code Date
B6.7 CM2450 B155B	Yes	6 August 2021	16 July 2021
L9 CM2350 L116B	Yes	-	28 March 2022
L9 CM2450 L126B	Yes	15 March 2021	15 February 2021
X15 CM2350 X114B	Yes	18 October 2021	14 October 2021
X15 CM2350 X116B	Yes	18 October 2021	14 October 2021
X15 CM2450 X124B	Yes	1 January 2021	11 May 2021
X15 CM2450 X134B	Yes	17 December 2021	15 December 2021
X15 CM2450 X142B	Yes	03 December 2024	25 November 2024

Document History

Date	Details
2021-1-29	Module Created
2021-6-25	Updated Table 1 for X15 CM2450 X124B.
2021-11-18	Non-Product Problem Solving (PPS)
2022-5-19	Updated Table 1.
2024-12-16	Added X15 CM2450 X142B to Product Affected list.
2024-12-18	Added X142B information to Table 1.