



Technical Service Bulletin

Technical Service Bulletin: TSB230190

Released Date: 12-Dec-2023

Internal Actuator Wiring Harness Intermittent Signal: Injector Fault Codes

Internal Actuator Wiring Harness Intermittent Signal: Injector Fault Codes

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISX15 CM2250
- ISX15 CM2250 SN
- ISX15 CM2350 X101
- QSX15 CM2250
- QSX15 CM2250 ECF
- QSX15 CM2250 ECF
- QSX15 CM2250 X115
- QSX15 CM2350 X105
- QSX15 CM2350 X106
- QSX15 CM2350 X118
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2350 X123B
- X15 CM2350 X125M
- X15 CM2350 X129B
- X15 CM2350 X130C
- X15 CM2350 X131
- X15 CM2350 X132C
- X15 CM2350 X140C
- X15 CM2450 X124B
- X15 CM2450 X134B

Issue Summary

Injectors are being replaced unnecessarily.

Symptom:

- Intermittent Fault Codes:

- 323
- 324
- 322
- 325
- 321
- 331
- 1139
- 1141
- 1142
- 1143
- 1144
- 1145

Root Cause:

- Valve crosshead contact with internal actuator wiring harness injector wire causing fatigue near crimp connector

Verification

Inspect internal actuator wiring harness for fractured or damaged areas and/or contact with the valve crosshead as seen in Figure 1. As a result of contact with the valve crosshead, the internal actuator wiring harness damage is **not** always obvious. Check for signs of damage to the wiring insulation near the crimp connector. See Figure 2.



Figure 1, View of Contact between Crosshead and Internal Actuator Wiring Harness.



Figure 2, View of Partial Insulation Break Near Crimp.

Resolution

If damage is found, replace injector internal actuator wiring harness, which has been improved to eliminate this failure mode. See corresponding Service Manual. Reference Procedure 019-063 in Section 19.

Document History

Date	Details
2023-9-26	Module Created
2023-12-12	Added additional wording to Resolution section.

Last Modified: 12-Dec-2023
