



Technical Service Bulletin

Technical Service Bulletin: TSB170063

Released Date: 04-Oct-2024

Fault Codes 3545 and 1887 Caused by Water or Soap Contaminants in Exhaust System

Fault Codes 3545 and 1887 Caused by Water or Soap Contaminants in Exhaust System

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- All 2010 and later products equipped with aftertreatment NOx sensors.

Issue

Symptom:

- Fault Code 3545 and 1887

Root Cause

- Water and soap are entering the exhaust system when vehicles are washed, contaminating the aftertreatment NOx sensor element or cracking the hot ceramic element.

Resolution

- Extra care should be taken to prevent any water or soap from entering the exhaust system.
 - Water can act as a transport agent to redeposit foreign contaminants such as road salt or corrosion onto aftertreatment NOx sensor element.
 - Soaps and power washing fluid contain chemicals known to contaminate aftertreatment NOx sensor element, possibly leading to aftertreatment NOx sensor malfunction.
- Inspect aftertreatment SCR drain hole for any blockage. See corresponding Service Manual. Reference Procedure 011-036 in Section 11.

Document History

Date	Details
2017-5-12	Module Created

Date	Details
2024-10-4	No content changed, checking TSB contents.

Last Modified: 04-Oct-2024
