



Technical Service Bulletin: TSB180046

Released Date: 10-Dec-2019

Broken Aftertreatment Diesel Oxidation Catalyst (DOC) Baffle: Fault Code 1664 or 1691

Broken Aftertreatment Diesel Oxidation Catalyst (DOC) Baffle: Fault Code 1664 or 1691

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- X12 CM2350 X119B
- X15 CM2350 X114B
- X15 CM2350 X116B

Issue

Symptom:

- Fault Code 1664 or 1691
- Possible noise coming from aftertreatment diesel oxidation catalyst (DOC)

Root Cause:

- Welding issues have been found inside inlet tube of aftertreatment DOC causing baffle breakage.
- See Figures 1 and 2 for examples of broken aftertreatment DOC baffles.



Figure 1, Broken Baffle in Inlet of Aftertreatment DOC.



Figure 2, Broken Aftertreatment DOC Baffle.

Verification

Troubleshoot fault code and inspect inlet of aftertreatment DOC for broken baffle.

Resolution

- If troubleshooting the applicable Fault Codes 1691 and 1664 lead to finding a cracked or broken baffle, replace the aftertreatment DOC. See corresponding Service Manual. Reference Procedure 011-049 in Section 11.
- If applicable Fault Codes 1691 and 1664 are **not** present, do **not** replace the aftertreatment DOC, even if a cracked or broken baffle is found. If a piece of the baffle is detached, as in Figure 2 above, remove detached baffle piece and install the aftertreatment DOC as is. See corresponding Service Manual. Reference Procedure 011-049 in Section 11.

Document History

Date	Details
2018-4-13	Module Created
2019-12-10	Updating Symptom, Product Affected, and Resolution section.

Last Modified: 10-Dec-2019
