



Technical Service Bulletin: TSB190114

Released Date: 17-Feb-2025

Shortened Suction Side Fuel Filter Life: Fault Code 559

Shortened Suction Side Fuel Filter Life: Fault Code 559

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- X12 CM2350 X119B
- X12 CM2450 X137B
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2450 X124B
- X15 CM2450 X134B
- X15 CM2450 X142B

Issue

Symptom:

- Customer repeatedly experiences plugged suction side fuel filter prior to required maintenance interval. See corresponding Operation and Maintenance Manual, Bulletin 5411187. Reference Procedure 359-008 in Section 3 for fuel filter maintenance interval.

Root Cause:

- Suction side fuel filter plugging

Verification

- Confirm suction side fuel filter is plugged. See corresponding Service Manual. Reference Procedure 006-020 in Section 6 to measure suction side fuel filter restriction.
- Confirm suction side fuel filter is a 10 micron fuel filter. Reference Table 1 for corresponding fuel filter part number.
- Confirm pressure side fuel filter restriction is within specification. Perform pressure side fuel filter restriction test. See corresponding Service Manual. Reference Procedure 005-236 in Section 5 to measure pressure side fuel filter restriction.

Resolution

New suction side fuel filter options for units repeatedly experiencing short suction side fuel filter life are available. New filter options offer adequate protection to the fuel system while extending suction side fuel filter life. See Table 1.

Service Instructions

Verify correct pressure side fuel filter is installed. Pressure side fuel filter, Part Number FF5971NN, with new suction side fuel filter, Part Number FS20337, is recommended, but pressure side fuel filter, Part Number FF5825NN or FF5971NN, **must** be used when utilizing a new suction side fuel filter.

Service Parts Availability

Table 1, Service Parts

Suction Side Filter Housing	Existing Suction Side Fuel Filter (10 Micron) Part Number	New Suction Side Fuel Filter Part Number	Pressure Side Fuel Filter Part Number
Standard PACCAR Housing	PACCAR K37-1029	PACCAR K37-1012	FF5825NN
	FLEETGUARD® FS20172	FLEETGUARD® FS20173	FF5825NN
Extended PACCAR Housing	PACCAR K37-1021	PACCAR K37-1022	FF5825NN
Davco 382 / FH 230	FLEETGUARD® FS19727	FLEETGUARD® FS19729, FS19728 ¹	FF5825NN
Davco 382 / FH 230 – Plus Size	FLEETGUARD® FS19764	FLEETGUARD® FS19905G, FS19765 ¹	FF5825NN
Davco 483	FLEETGUARD® FS20139	FLEETGUARD® FS20140	FF5825NN
Davco 485	FLEETGUARD® FS20083/FS20385	FLEETGUARD® FS20337	FF5825NN
Davco 498	FLEETGUARD® FS20083/FS20385	FLEETGUARD® FS20337	FF5825NN
Western Star	FLEETGUARD® FS19551	FLEETGUARD® FS19532	FF5825NN
MCI Coach CM2350	FLEETGUARD® FS2716	FLEETGUARD®	FF5825NN
		FS19905G, FS19765 ¹	
MCI Coach CM2450	FLEETGUARD® FS19764	FLEETGUARD®	FF2338NN
		FS19905G, FS19765 ¹	

¹FS19728 and FS19765 are preferred where available.

If a part number is **not** referenced in Table 1, contact local Cummins Inc. representative for assistance in obtaining correct suction side fuel filter part number.

Document History

Date	Details
2019-6-27	Module Created
2019-8-8	Added statement about pessure side fuel filter, Part Number FF5825NN. Added Extended PACCAR Housing information to Table 1.
2021-6-28	Updated Product Affected Section.
2022-11-11	Added X12 CM2350 X119B, X12 CM2450 X137B, and updated Table 1.
2024-10-28	Added X15 CM2450 X142B to Product Affected list.
2025-2-6	Updated Service Instruction section and Table 1.

Last Modified: 17-Feb-2025
