



Technical Service Bulletin

Technical Service Bulletin: TSB210110

Released Date: 23-Jul-2026

New Turbocharger Adapter and O-ring

New Turbocharger Adapter and O-ring

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2350 X123B
- X15 CM2350 X125M
- X15 CM2450 X124B
- X15 CM2450 X134B

Description of Change

This document announces the release of a new turbocharger adapter part number and o-ring, option CA1713, to improve sealing between turbocharger adapter and turbocharger.

Service Parts Availability

Service parts are available. See Table 1 below for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
O-ring	-	-	-	2863701
Turbocharger Adapter	3691072	Yes	Yes	5687906

Part Compatibility

- Turbocharger adapter, Part Number 5687906, **must** be accompanied by new o-ring, Part Number 2863701.
- O-ring, Part Number 2863701, is **not** able to be used with existing turbocharger adapter, Part Number 3691072.
- When assembling the turbocharger adapter Part Number 3691072, apply a bead of silicone sealant, Part Number 3164067, in the adapter to turbocharger joint.

Part Identification

- New Turbocharger Adapter was introduced with ESN first 80365876 and can be identified by the groove on the v-band mating face.
- New O-ring can be identified by the pink color.

Part Inventory Action

Use existing part number inventory before using the new part number.

Document History

Date	Details
2021-5-21	Module Created
2026-7-20	Updated Part Compatibility and Part Identification

Last Modified: 23-Jul-2026