



Technical Service Bulletin: TSB210192

Released Date: 27-Feb-2023

Engine Wiring Harness Malfunctions Causing Datalink Fault Codes

Engine Wiring Harness Malfunctions Causing Datalink Fault Codes

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISX12 CM2350 X102
- ISX15 CM2350 X101
- X12 CM2350 X119B
- X12 CM2450 X137B
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2350 X130C
- X15 CM2350 X140C
- X15 CM2450 X124B
- X15 CM2450 X134B

Issue Summary

Symptom:

- Amber Check Engine Light
- A fault code is active or has more than one inactive count within the last twenty-five engine operating hours from the following list: 1894, 2771, 3232, 3868, 3911, 4151, 4152, 4572, 4677, 5177, or 6688.

Root Cause:

- Use of dielectric grease in connector
- Water intrusion into connectors
 - OEM after treatment jumper wiring harness
 - After treatment connectors
 - 14-pin OEM crossover connector

Verification

1. If checking a connector while following the published troubleshooting tree, visually inspect the connector for evidence of dielectric grease usage. See Figure 1 below.



Figure 1, Dielectric Grease in Connector.

2. If checking a 14-pin connector while following the published troubleshooting tree, inspect connector for evidence of water intrusion or corrosion. See Figure 2 and Figure 3 below.



Figure 2, Evidence of Water Intrusion or Corrosion.



Figure 3, Evidence of Water Intrusion or Corrosion.

Resolution

- If there is evidence of dielectric grease usage in a connector, remove the dielectric grease and clean the connector.

- If there is evidence of water intrusion through into a connector, follow the corresponding service manual procedure to repair or replace the connector.

Document History

Date	Details
2021-8-30	Module Created
2023-2-26	Added Fault Code 5177.

Last Modified: 27-Feb-2023
