



Technical Service Bulletin: TSB210281

Released Date: 16-Dec-2021

Lubricating Oil Leak from Upper Gear Cover

Lubricating Oil Leak from Upper Gear Cover

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2450 X124B
- X15 CM2450 X134B

Issue Summary

Symptom:

- Lubricating oil Leaks from the upper gear cover

Root Cause:

- Loss in retention of the upper gear cover capscrew load

Verification

Verify lubricating oil is leaking from the interface of the upper gear cover and the gear housing.

Resolution

- Do **not** remove the upper gear cover.
- Torque all the upper gear cover capscrews. See corresponding Service Manual. Reference Procedure 001-079 in Section 1.
- Clean lubricating oil residue off upper gear cover and surrounding components.
- If the engine contains idler pulley bracket, Option FA1611 or FA1608:
 - Remove 3 idler pulley bracket mounting capscrews.
 - Clean capscrews.
 - Install with Loctite® 242, Cummins® Part Number 3824040, and torque to 31 N•m [23 ft-lb].
 - Final torque **must** be achieved within 10 minutes of applying Loctite® to the first idler pulley bracket capscrew.

- Operate the engine to normal operating temperature. Check for leaks and proper operation.

Document History

Date	Details
2021-12-16	Module Created

Last Modified: 16-Dec-2021
