



Technical Service Bulletin

Technical Service Bulletin: TSB220065

Released Date: 01-Apr-2022

SmartAccel™ Stumble, Misfire, or Hesitation During a Snap Throttle with a Stationary Vehicle

SmartAccel™ Stumble, Misfire, or Hesitation During a Snap Throttle with a Stationary Vehicle

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISX12 CM2350 X102
- ISX15 CM2350 X101
- X12 CM2350 X119B
- X12 CM2450 X137B
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2450 X124B
- X15 CM2450 X134B

Issue Summary

Symptom:

- Unit experiences a stumble, misfire, or hesitation during a snap throttle while stationary.

Root Cause:

- The SmartAccel™ feature can limit torque ramp rate of the engine when the vehicle is **not** moving and is **not** in gear; therefore, the SmartAccel™ feature can limit the torque output of the engine during these events.

Verification

- Disable the SmartAccel™ feature using INSITE™ electronic service tool.
- Run the snap throttle to verify stumble, misfire, or hesitation is no longer present.

Resolution

Review Technical Service Bulletin, SmartAccel™ Feature Release and Initial Tuning Guide, TSB160055 to verify the SmartAccel™ feature is programmed correctly. If so, review the vehicle specifications with the OEM and/or customer to see if the use of SmartAccel™ is needed or if SmartAccel™ could be disabled.

Document History

Date	Details
2022-3-30	Module Created

Last Modified: 01-Apr-2022
