



Technical Service Bulletin

Technical Service Bulletin: TSB240169

Released Date: 03-Oct-2024

Air Handling Performance Test Freezes after Engine Start: Fault Code 1117

Air Handling Performance Test Freezes after Engine Start: Fault Code 1117

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B6.7 CM2350 B121B
- B6.7 CM2450 B155B
- L9 CM2350 L116B
- L9 CM2450 L126B
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2450 X124B
- X15 CM2450 X134B
- X15 CM2450 X142B
- X12 CM2450 X137B

Issue Summary

Symptom:

- Air Handling Performance Test does **not** continue after engine start and does **not** display an abort message in the test screen status box.
- Fault Code 1117
- Air Handling Performance Test did not complete

Root Cause:

- Battery voltage dropped out during engine cranking, causing the ECM to reset

Verification

- Air Handling Performance Test does **not** continue 20 seconds after engine start and does **not** display an abort message
- Fault Code 1117 is active

Resolution

- Check the ECM and block ground straps for loose or corroded connections. Reference TSB220192.
- Load test the batteries. See equipment manufacturer service information.

Document History

Date	Details
2024-8-28	Module Created
2024-10-3	Fixed reference to L123B to L126B in Product Affected list.

Last Modified: 03-Oct-2024