



Technical Service Bulletin

Technical Service Bulletin: TSB250072

Released Date: 07-Apr-2025

Accelerator Pedal Intermittent Drop Out with No Fault Code

Accelerator Pedal Intermittent Drop Out with No Fault Code

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- L9 CM2350 L116B
- L9 CM2350 L119B
- L9 CM2350 L123B
- L9 CM2450 L126B
- L9 CM2450 L169B
- X12 CM2350 X119B
- X12 CM2450 X137B
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2350 X123B
- X15 CM2350 X129B
- X15 CM2450 X124B
- X15 CM2450 X134B
- X15 CM2450 X142B
- X15 CM2450 X153B
- X15 CM2450 X154B
- X15 CM2450 X155B

Issue Summary

- In units with analog accelerator pedals, damage or improper connection to the engine control module (ECM) can cause a voltage short preventing fueling.

Symptoms

- Intermittent drop out of the accelerator pedal. Fueling will return after the operator has completely released and reapplied the pedal. This event may occur multiple times, often every few seconds.

- No active fault code.

Verification

- Confirm unit is utilizing an analog pedal and **not** a pulse width modulation pedal.
 - This can be found in INSITE™ electronic service tool under feature and parameters accelerator type.
- Confirm no new fault codes are appearing with the above symptoms.
- Inspect Accelerator Pedal Sensor 1 and 2 pins on the ECM. Reference wiring diagram for correct pins.

Resolution

- See corresponding Service Manual. Reference Procedure 019-031 in Section 19 and inspect for reuse.
- If engine control module (ECM) pin damage is found, repair or replace damaged components or pins.

Document History

Date	Details
2025-3-28	Module Created

Last Modified: 07-Apr-2025
