



Technical Service Bulletin

Technical Service Bulletin: TSB250211

Released Date: 26-Nov-2025

J1939 Data Link Diagnostic Tool Not Available in INSITE™ Electronic Service Tool Version 9.1.1.92

J1939 Data Link Diagnostic Tool Not Available in INSITE™ Electronic Service Tool Version 9.1.1.92

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B6.7 CM2350 B121B
- B6.7 CM2450 B155B
- L9 CM2350 L116B
- L9 CM2350 L123B
- L9 CM2450 L126B
- X12 CM2350 X119B
- X12 CM2450 X137B
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2450 X124B
- X15 CM2450 X134B
- X15 CM2450 X142B

Issue Summary

Symptom:

- The J1939 Data Link Diagnostic Tool is not available.

Root Cause:

- Latest revision of the J1939 Data Link Diagnostic Tool is not recognized in INSITE™ electronic service tool version 9.1.1.92.

Verification

The J1939 Data Link Diagnostic Tool under the Tools tab in INSITE is greyed out.

Resolution

Download and install the Inline 7 + USB Link 3 drivers version 3.3.0.2 or newer. Reference the link below:

<https://www.cummins.com/support/digital-products-and-services-support/inline-support>

Manually open the application by using the following directory in File Explorer.

C:\Program Files

(x86)\Cummins\J1939DataLinkDiagnosticTool\J1939DatalinkDiagnosticTool.exe

Document History

Date	Details
2025-11-25	Module Created

Last Modified: 26-Nov-2025
