

Fault Code: Multiple F

Multiple Fault Code F on the Engine Harness

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: Multiple F PID(P): SPN: FMI: Lamp: SRT: 00-381	On engines without CENSE™, the common return fails internal to the ECM, affecting pins 17 and 18 on the engine harness, and pins 11 and 21 on the OEM interface harness.	Multiple fault codes.

©Cummins Inc

Circuit Description

The ECM supplies all of the engine pressure sensors on the engine harness with +5 VDC from either pin 5 or pin 6. The ECM has common returns for all of the engine pressure sensors and all of the temperature sensors on either pin 17 or pin 18. A failure on either of these wires will cause

multiple fault codes.

Component Location

Refer to the engine diagrams.

Shoptalk

Look for open circuits in the common supply and return wires and shorts from battery or ground to the supply and return wires or defective ECM power supply. A failed pressure sensor can cause multiple fault codes.

Refer to Troubleshooting Fault Code t05-mfc05 (/qs3/pubsys2/xml/en/procedures/19/19-t05-mfc05.html)

Last Modified: 19-Aug-2010
