



Technical Service Bulletin

Technical Service Bulletin: tsb100755

Released Date: 09-Oct-2008

New Exhaust Manifold Gasket and Capscrew

New Exhaust Manifold Gasket and Capscrew

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin releases a new exhaust manifold capscrew and a new exhaust manifold gasket for the ISM, ISMe, and QSM11 engine series. Marine applications will use the new exhaust manifold capscrew **only**. The new exhaust manifold capscrew supersedes the present exhaust manifold capscrew. The new exhaust manifold gasket will only be installed on cylinder ports 1 and 6; ports 2, 3, 4, and 5 will use the present graphite style exhaust manifold gasket.

The new exhaust manifold gasket is a multi-layer steel design that does not have the graphite coating that is on the present exhaust manifold gasket. The use of the new style gaskets on ports 1 and 6 of the manifold alleviates some of the shear forces acting on all of the exhaust manifold gaskets during the expansion and contraction of the exhaust manifold during engine operation. The new exhaust manifold gaskets went into production on June 13, 2008, with an engine serial number (ESN) first of 35231673.

The new exhaust manifold capscrew has a redesigned thread profile which improves robustness and overall performance. The new exhaust manifold capscrew was implemented into production in January, 2007, and again for use on engines built prior to January 1, 2007 on April 1, 2008.

See Table 1 for the new and old exhaust manifold gasket and capscrew part numbers.

Table 1: New and Old Exhaust Manifold Capscrew and Gasket

New Part Number	Description	Old Part Number	Quantity Required
3955339	Exhaust Manifold Gasket (Used at Port 1 and 6)	3328948	2
4965698	Exhaust Manifold Capscrew	3818121	12

Last Modified: 09-Oct-2008