



Technical Service Bulletin

Technical Service Bulletin: tsb100875

Released Date: 16-Jul-2014

New Intermediate Piston Ring

New Intermediate Piston Ring

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces the new ISX semi-inlaid intermediate piston ring. The design was changed from a full blitz chrome 2nd ring to a semi-inlaid 2nd ring.

The semi-inlaid ring has a sharp bottom edge, compared to the chamfered bottom edge of the full blitz chrome ring it replaces. This feature allows the ring to scrape the liner more effectively than the previous ring, which helps prevent engine oil from moving above the top ring. The new semi-inlaid ring also has a larger end gap (2.13 mm [.084 in] vs. 1.23 mm [.048 in]). This larger end gap allows for a slight increase in blowby, which in turn reduces intermediate ring gas pressure, providing improved top ring seating.

Table 1: Semi-inlaid Piston Ring Information

New Piston Ring Kit Part Number	Old Piston Ring Part Number	Engine Serial Number (ESN) First	Start Date
2869635	3681078	79383594	7/22/09

Table 2: Piston Ring Kit Information

New Piston Ring Part Number	Old Piston Ring Kit Part Number	Engine Serial Number (ESN) First	Start Date
2881682	4089406	79383594	7/22/09

Note : This is a product improvement and is not subject to TRP or Campaign actions.

Document History

Date	Details
2014-7-14	none

