



Technical Service Bulletin

Technical Service Bulletin: tsb100886

Released Date: 17-Dec-2009

New Crankshaft

New Crankshaft

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin supersedes Service/Parts Topic 05T1-13. Please replace Service/Parts Topic 05T1-13 with this Service/Parts Topic.

This Technical Service Bulletin introduces the new ISX crankshaft and documents the crankshaft supersessions and compatibility.

Crankshaft Part Number	Description	Compatible Part Numbers
3681073	Crankshaft used on first 950 ISX engines, different style tone wheel than used on present design.	None. Must use 3681073.
3681911	Production crankshaft from January, 1999 through June, 2004.	4923646, 4925762
4923646	Temporary crankshaft part number, can be found on engines built from June, 2004 through December, 2004.	3681911, 4925762
4925762	New production crankshaft part number, includes the removal of rear lightening hole as well as non-ground main bearing fillets. Functionally the same as 3681911 and 4923646.	3681911, 4923646

