



Technical Service Bulletin

Technical Service Bulletin: TSB120190

Released Date: 20-Jun-2012

New Front Cover with New O-Ring Seal

New Front Cover with New O-Ring Seal

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

©Cummins Inc



01800029

This document announces a new front cover for ISB and QSB engines.

The new front cover now includes an o-ring seal around the oil pressure switch cavity. Historically, RTV was used to seal this joint. This change prevents the possibility of excess RTV entering the oil cavity from the oil pressure switch cavity seal. The new design is shown above.

Note : The old parts also contain a recess around the oil pressure sensor cavity, this recess is not suitable for the o-ring seal.

Service Instructions

- Old Part - When service intervention requires sealing of the old front cover, the old part should be sealed (as before) by applying RTV sealant to the mating faces including the mating faces around the oil pressure sensor cavity.
- New Part - When service intervention requires sealing of the new front cover, the new part should be sealed by applying RTV sealant to the mating faces, **not** including the mating faces around the oil pressure sensor cavity. The mating faces around the oil pressure sensor cavity require **only** the o-ring seal.

Table 1, Old and New Front Cover Part Numbers

Description	Old Part Number	New Part Number	O-Ring Part Number
Front Gear Cover	5255790	5289175	3958414
Front Gear Cover	5255791	5289176	3958414
Front Gear Cover	5255792	5289177	3958414
Front Gear Cover	5258750	5289178	3958414
Front Gear Cover	5258751	5289179	3958414
Front Gear Cover	5258752	5289180	3958414
Front Gear Cover	5258753	5289181	3958414

Table 2, ESN First of Engine with New Front Cover

ESN First	Build Date	Plant
22047803	April 25, 2012	Darlington Engine Plant

Document History

Date	Details
2012-5-24	Module Created

Last Modified: 20-Jun-2012
