



Technical Service Bulletin

Technical Service Bulletin: TSB130001

Released Date: 18-Jan-2013

New ISX15 and QSX15 Cylinder Block Assembly

New ISX15 and QSX15 Cylinder Block Assembly

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

The purpose of this document is to notify the field of a new cylinder block assembly for all ISX15 and QSX15 engines. The new cylinder block assembly is backward compatible with all previous 15L engines. The new cylinder block assembly contains the factory-shimmed cylinder liner assembly. The design changes to the cylinder liner were made to address cylinder head gasket combustion seal leaks and counterbore mid-stop fretting.

New Part Number	Description	Old Part Number
4311628	Block, Cylinder (Service Assembly)	4311630
4311625	Block, Cylinder (Production Assembly)	4311622
4309390	Kit, Cylinder Block (Service Assembly)	2882088

Cylinder Block Kit, Part Number 4309390, contains a dressed cylinder block, Part Number 4311628, which includes main caps, the factory-shimmed cylinder liner design, and Cylinder Block Hardware Kit, Part Number 4955501.

Jamestown Engine Plant implemented the new cylinder block assembly into production in phases. The first phase targeted engines built for Australia and began on 22 May 2012. The engine serial number (ESN) first is 79583578. The second phase targeted ISX15 CM2250 engines and began on 4 September 2012. The engine serial number (ESN) first is 79608640.

Document History

Date	Details
2013-1-2	Module Created

