



Technical Service Bulletin

Technical Service Bulletin: TSB190074

Released Date: 09-May-2019

Western Star Charging System Alternator Bracket Interference with Water Pump

Western Star Charging System Alternator Bracket Interference with Water Pump

Warranty Statement

The information in this document authorizes specific changes to the repair practice for failures covered under product warranty coverages.

Contents

Products Affected

Engine:

- Signature ISX CM570

Chassis

- Western Star

Issue

Symptom:

- New design water pump is **not** compatible with Western Star chassis charging system alternator bracket.

Root Cause:

- Charging system alternator bracket is **not** compatible dimensionally with the new design water pump.

Verification

New water pump is **not** be able to be mounted with existing alternator bracket.

Resolution

A new Western Star charging system alternator bracket has been released that is compatible with the new water pump.

Service Instructions

New charging system alternator bracket **must** be ordered if new water pump is to be installed. See Table 1 below for part number information.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
WATER PUMP	4923759	Yes	Yes	5484604
ALTERNATOR BRACKET	80204-3414	Yes	Yes	01-34949-000

Document History

Date	Details
2019-5-8	Module Created