

# Fault Code: Multiple B

## Multiple Fault Code B on the Engine Harness

 Printable Version

### Overview

| Codes                                                                                                | Reason                                                                                                                                                                                                                                                            | Effect                       |
|------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|
| <p>Fault Code: Multiple B</p> <p>PID(P):</p> <p>SPN:</p> <p>FMI:</p> <p>Lamp:</p> <p>SRT: 00-381</p> | <p>On engines with an electronic fuel pump, the supply voltage from pin 5 of the engine harness has:</p> <ul style="list-style-type: none"><li>Failed internally in the ECM</li><li>Been shorted to ground</li><li>An open circuit external to the ECM.</li></ul> | <p>Multiple fault codes.</p> |

©Cummins Inc

Circuit Description

The ECM supplies all of the engine pressure sensors on the engine harness with +5 VDC from either pin 5 or pin 6. The ECM has common returns for all of the engine pressure sensors and all of the temperature sensors on either pin 17 or pin 18. A failure on either of these wires will cause multiple fault codes.

## Component Location

Refer to the engine diagrams.

## Shoptalk

Look for open circuits in the common supply and return wires and shorts from battery or ground to the supply and return wires or defective ECM power supply. A failed pressure sensor can cause multiple fault codes.

Refer to Troubleshooting Fault Code t05-mfc01 (</qs3/pubsys2/xml/en/procedures/19/19-t05-mfc01.html>)

---

**Last Modified: 19-Aug-2010**

---