



Installation Instruction

Installation Instruction Number: 6583693

Released Date: 18-sep-2024

Variable Geometry Turbocharger Actuator Installation

Variable Geometry Turbocharger Actuator Installation

Product Affected

Variable Geometry Turbocharger Actuator

Issue Summary

Variable Geometry Turbocharger Actuators have been improperly diagnosed as faulty after incorrect install or calibration steps were performed. This document is intended to reduce the risk of errors while calibrating a turbocharger actuator. The corresponding Service Manual **must** be referenced for detailed turbocharger actuator installation and calibration procedure.

Symptom:

- “Failed” message received on Turbocharger Electric Actuator Installation and Calibration Test in the electronic service tool
- Active fault code

Root Causes:

- The variable geometry turbocharger actuator was mounted to the turbocharger during the Install/Prealign Actuator step.
- Improper alignment of turbocharger sector gear while mounting the turbocharger actuator.

Resolution

- See corresponding Service Manual. Reference Procedure 010-134 in Section 10. All steps **must** be followed in order.
- If the Variable Geometry Turbocharger Actuator Install or Calibrate steps do **not** pass, the installation procedure **must** be started over from the beginning.
- The Variable Geometry Turbocharger Actuator **must** be removed, unplugged for 30 seconds, and the turbocharger sector gear placed into the correct fully clockwise position.

Document History

Date	Details
2024-9-18	Module Created

Last Modified: 18-Sep-2024