



Technical Service Bulletin

Technical Service Bulletin: TSB150171

Released Date: 24-Sep-2020

High Mount / Mid Mount - Angled Turbochargers with Top Mount Turbocharger Actuator - Lubricating Oil Found at Turbocharger Sector Gear and Turbocharger Actuator Gear When Turbocharger Actuator is Removed

High Mount / Mid Mount - Angled Turbochargers with Top Mount Turbocharger Actuator - Lubricating Oil Found at Turbocharger Sector Gear and Turbocharger Actuator Gear When Turbocharger Actuator is Removed

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B6.7 CM2350 B121B
- B6.7 CM2350 B135B
- B6.7 CM2350 B148B
- B6.7 CM2450 B155B
- ISB6.7 CM2350 B101
- ISL9 CM2350 L101
- L9 CM2350 L116B
- L9 CM2350 L119B
- L9 CM2350 L123B
- L9 CM2450 L126B
- X12 CM2350 X119B
- X12 CM2450 X137B
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2350 X123B
- X15 CM2350 X129B
- X15 CM2450 X124B
- X15 CM2450 X134B

Issue

During troubleshooting on engines equipped with high mount turbochargers with top mount turbocharger actuators, lubricating oil has been found around the turbocharger sector gear and the variable geometry turbocharger actuator gear. This is normal and does **not** indicate a malfunction has occurred.

Verification

See Figure 1 and Figure 2 below for examples of acceptable lubricating oil leakage near the turbocharger sector gear and the variable geometry turbocharger actuator gear.

©Cummins Inc



Figure 1, Acceptable Lubricating Oil Leakage Around the Turbocharger Sector Gear



Figure 2, Acceptable Lubricating Oil Leakage Around the Variable Geometry Turbocharger Actuator Sector Gear

Resolution

Turbochargers and variable geometry turbocharger actuators should **not** be replaced if lubricating oil is found as shown in Figure 1 and Figure 2 above. For confirmation of actual lubricating oil leak from the turbocharger or turbocharger actuator:

- See the corresponding Service Manual. Reference Procedure 010-033 and 010-134 in Section 10.

Published troubleshooting should be continued for the symptom(s) or fault code(s) present.

Document History

Date	Details
2015-10-26	Module Created
2016-1-22	Added ISB6.7 CM2350 B101 to Product Affected and updated title.
2016-9-21	Added B6.7 CM2350 B121B
2020-9-24	Added several engines.

