



Technical Service Bulletin

Technical Service Bulletin: TSB170031

Released Date: 29-Aug-2017

Fault Code 6255 Present With No Other Fault Codes and Possible Diesel Exhaust Fluid (DEF) Lamp Illumination

Fault Code 6255 Present With No Other Fault Codes and Possible Diesel Exhaust Fluid (DEF) Lamp Illumination

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B6.7 CM2350 B121B
- ISB6.7 CM2350 B101
- ISL9 CM2350 L101
- ISX12 CM2350 X102
- ISX15 CM2350 X101
- L9 CM2350 L116B
- X15 CM2350 X114B
- X15 CM2350 X116B

Issue

Symptom:

- **Only** Fault Code 6255 present (active).
- Diesel exhaust fluid (DEF) lamp may be illuminated.

Root Cause:

- Engine control module (ECM) calibration code issue.

Resolution

- Calibrate ECM using a January 2017, or later, INCAL™ DVD. Reference ECM Calibration Revision History on QuickServe™ Online for more information.
- See corresponding Service Manual. Reference Procedure 019-032 in Section 19.
- If any fault codes other than Fault Code 6255 are active, troubleshoot fault codes using corresponding troubleshooting tree.

- Run engine for two minutes after ECM calibration to allow DEF diagnostic to run. Key OFF and key ON; DEF lamp should clear.

Document History

Date	Details
2017-3-17	Module Created
2017-8-23	Changed title; added: "Possible Diesel Exhaust Fluid (DEF) Lamp Illumination". Updated Symptom and Resolution section.

Last Modified: 29-Aug-2017
