



Technical Service Bulletin: TSB170047

Released Date: 18-Jan-2018

Aftertreatment System Alignment Arrows Misaligned on Firetruck Applications

Aftertreatment System Alignment Arrows Misaligned on Firetruck Applications

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Products Affected:

- B6.7 CM2350 B121B
- L9 CM2350 L116B
- X15 CM2350 X114B
- X15 CM2350 X116B

OEMs Affected:

- Pierce
- Vanhool

Issue

This document describes required misalignment of aftertreatment alignment arrows **only** on firetruck applications.

Verification

Alignment arrows on aftertreatment diesel particulate filter (DPF) and aftertreatment decomposition tube are intentionally misaligned by approximately 10 degrees. See Figure 1 below.




Figure 1, Alignment Arrows.

Resolution

⚠ CAUTION ⚠

If aftertreatment DPF and aftertreatment decomposition tube alignment arrows are in alignment, differential pressure sensor tube connected to aftertreatment decomposition tube will not fit properly and can become kinked and/or bent.

- Misalignment of aftertreatment DPF and aftertreatment decomposition tube is required to allow for adequate aftertreatment system clearance in this application.
- Prior to loosening or removal of aftertreatment v-band clamp, aftertreatment DPF, or aftertreatment decomposition tube; an orientation reference line **must** be drawn across aftertreatment DPF, v-band clamp, and decomposition tube to aid in assembly.
- Use orientation reference lines added prior to loosening or removal to assist in correct differential pressure sensor tube alignment during assembly.

Document History

Date	Details
2017-4-7	Module Created
2018-1-18	Added affected OEMs

