



Technical Service Bulletin

Technical Service Bulletin: TSB220159

Released Date: 01-Aug-2022

Air Handling Performance Test and NOx Sensor Diagnostic Steps with Engine Control Module (ECM) Calibration Code Revision with DEF Header Calibration Revision

Air Handling Performance Test and NOx Sensor Diagnostic Steps with Engine Control Module (ECM) Calibration Code Revision with DEF Header Calibration Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B6.7 CM2450 B155B
- B6.7 CM2350 B121B
- L9 CM2350 L116B
- L9 CM2450 L126B
- X12 CM2350 X119B
- X12 CM2450 X137B
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2450 X124B
- X15 CM2450 X134B

Issue Summary

The aftertreatment engine control module (ECM) calibration code revision with DEF header calibration revision (See Technical Service Bulletin, Fault Codes 3868, 4572 and 4677 Caused by Diesel Exhaust Fluid (DEF) Header Malfunction, TSB210187) does **not** contain the Air Handling Performance Test, the Aftertreatment Intake NOx Sensor Test, or the Aftertreatment Outlet NOx Sensor Test. Troubleshooting may prompt the user to run these diagnostics, and if the unit has the ECM calibration code revision with DEF header calibration revision these diagnostic tests will **not** be available in INSITE™ electronic service tool.

Verification

If troubleshooting is directing to run the Air Handling Performance Test, the Aftertreatment Intake NOx Sensor Test, or the Aftertreatment Outlet NOx Sensor Test and the diagnostic test needed is **not** appearing in INSITE™ electronic service tool follow the Resolution section below.

Resolution

To complete the needed diagnostics the original base ECM calibration **must** be downloaded.

Service Instructions

1. See the engine data plate for the original base ECM calibration code.
2. Navigate the Calibration Revisions on QuickServe® Online and search the Description column for the ECM calibration code that has the needed diagnostic test.
3. Download the ECM calibration code with the needed diagnostic test from QSOL and complete the needed troubleshooting.
4. Once repair is completed, download the ECM calibration code revision with DEF header calibration revision (See Technical Service Bulletin, Fault Codes 3868, 4572 and 4677 Caused by Diesel Exhaust Fluid (DEF) Header Malfunction, TSB210187).

Document History

Date	Details
2022-7-29	Module Created

Last Modified: 01-Aug-2022
